Rimage 2000i 6.5-8.0 Service Pack 1

This document describes the changes made by Rimage 2000i 6.5 - 8.0 Service Pack 1.

Compatibility

Rimage 2000i 6.5 – 8.0 Service Pack 1 is compatible only with Rimage systems running

- **Rimage 2000i Software** versions 7.0, 7.1 and 7.4

or

- **Rimage OfficeNET Software Suite (OSS)** versions 6.5, 7.0, 7.4 and 8.0

Changes to Rimage Software Components

All software versions

- Provides support for the AD-5200A CD/DVD recorder.
- Resolved an issue with using the Hexalock plug-in with the AD-5170A and AD-5200A recorders. (Rimage reference #8333).

Rimage 2000i and OSS version 7.0

- Resolved an issue displaying the track list when requested in the *Copy CD* dialog. (Rimage reference #8410).

Rimage 2000i version 7.1

- Resolved an issue with recording DVD+R media on AD-5170A and AD-5200A recorders. (Rimage reference #6848).

Rimage OSS and Rimage 2000i version 7.4

- Resolved an issue where Production Server was failing when the system was processing heavy disk I/O. (Rimage reference #8210).
- Resolved an issue where some recorders could not be updated using the Rimage 2000i updater utility. (Rimage reference #7049).
- Resolved an issue where the first print job submitted after a reboot failed. (Rimage reference #7112).

Rimage OSS version 8.0

- Resolved an issue where Production Server was failing when the system was processing heavy disk I/O. (Rimage reference #8210).
- Resolved an issue where, when a write failure occurred during recording, the system was not attempting to rewrite the data. (Rimage reference #8308).